







B K Infotech

Regd. Office : 506 Swapna Siddhi, Akurli Road, kandivali East Mumbai - 400 064, India.
Support : | W : <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1116																														
Priority :	High																													
Created By :	Admin - Kalpesh Jain																													
Complaint Mob. No. :	9322290928																													
Technician Name :	Ganesham Mudaliar	Technician Mobile :	9967005871																											
Ticket Type :	New Installation	Date & Time :	25-10-2019 06:55:13																											
Vendor Details :																														
Company Name/Client Name :	Shree Sai Corporate Park Premises Co-Op Society	Customer's Mobile :	9322290928	Name :	Shree Sai Corporate Pandeyji																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Cctv Amc Service																													
Complain :	receiver + sender install																													
Technician Comment :	sender and resiver install also adapter install lift camera issue solve																													
Complain Operator :	Desktop - Kalpesh Jain																													
Remark :	sender and resiver install also adapter install lift camera issue solve																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-11-2019 05:59:50</td><td>GaneshamMudaliar</td><td>Completed</td><td>sender and resiver install also adapter install lift camera issue solve</td><td></td></tr><tr><td>31-10-2019 09:11:52</td><td>GaneshamMudaliar</td><td>Work Pending</td><td>need to install adapter</td><td></td></tr><tr><td>25-10-2019 06:55:26</td><td>GaneshamMudaliar</td><td>New</td><td></td><td>-</td></tr><tr><td>25-10-2019 06:55:14</td><td>GaneshamMudaliar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-11-2019 05:59:50	GaneshamMudaliar	Completed	sender and resiver install also adapter install lift camera issue solve		31-10-2019 09:11:52	GaneshamMudaliar	Work Pending	need to install adapter		25-10-2019 06:55:26	GaneshamMudaliar	New		-	25-10-2019 06:55:14	GaneshamMudaliar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
08-11-2019 05:59:50	GaneshamMudaliar	Completed	sender and resiver install also adapter install lift camera issue solve																											
31-10-2019 09:11:52	GaneshamMudaliar	Work Pending	need to install adapter																											
25-10-2019 06:55:26	GaneshamMudaliar	New		-																										
25-10-2019 06:55:14	GaneshamMudaliar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-11-2019 01:49:11</td><td>Manish Dhangar</td><td>1 lift camera Service 1 camera angle shapting</td></tr><tr><td>17-10-2019 10:19:40</td><td>Manish Dhangar</td><td>1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-11-2019 01:49:11	Manish Dhangar	1 lift camera Service 1 camera angle shapting	17-10-2019 10:19:40	Manish Dhangar	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																
Date Time	Technician Name	Remark																												
19-11-2019 01:49:11	Manish Dhangar	1 lift camera Service 1 camera angle shapting																												
17-10-2019 10:19:40	Manish Dhangar	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																												