

B K Infotech

Regd. Office : 506 Swapna Siddhi, Akurli Road, kandivali East Mumbai - 400 064, India.
Support : | W : <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1209																									
Priority :	High																								
Created By :	Admin - Kalpesh Jain																								
Complaint Mob. No. :	9322290928																								
Technician Name :	Manish Dhangar	Technician Mobile :	9136841712																						
Ticket Type :	Complain	Date & Time :	19-11-2019 01:49:11																						
Vendor Details :																									
Company Name/Client Name :	Shree Sai Corporate Park Premises Co-Op Society	Customer's Mobile :	9322290928	Name :	Shree Sai Corporate Pandeyji																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	camera service cctv																								
Complain :	lift camera issue																								
Technician Comment :	1 lift camera Service 1 camera angle shapting																								
Complain Operator :	Desktop - Kalpesh Jain																								
Remark :	1 lift camera Service 1 camera angle shapting																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-11-2019 09:43:26</td><td>Manish Dhangar</td><td>Completed</td><td>1 lift camera Service 1 camera angle shapting</td><td></td></tr><tr><td>19-11-2019 01:49:21</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-11-2019 01:49:12</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-11-2019 09:43:26	Manish Dhangar	Completed	1 lift camera Service 1 camera angle shapting		19-11-2019 01:49:21	Manish Dhangar	New		-	19-11-2019 01:49:12	Manish Dhangar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
22-11-2019 09:43:26	Manish Dhangar	Completed	1 lift camera Service 1 camera angle shapting																						
19-11-2019 01:49:21	Manish Dhangar	New		-																					
19-11-2019 01:49:12	Manish Dhangar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-10-2019 06:55:13</td><td>GaneshamMudaliar</td><td>sender and resiver install also adapter install lift camera issue solve</td></tr><tr><td>17-10-2019 10:19:40</td><td>Manish Dhangar</td><td>1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-10-2019 06:55:13	GaneshamMudaliar	sender and resiver install also adapter install lift camera issue solve	17-10-2019 10:19:40	Manish Dhangar	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup											
Date Time	Technician Name	Remark																							
25-10-2019 06:55:13	GaneshamMudaliar	sender and resiver install also adapter install lift camera issue solve																							
17-10-2019 10:19:40	Manish Dhangar	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																							