




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2347					
Priority :	High				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9819049156				
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965	
Ticket Type :	Complain	Date & Time :	03-12-2020 12:37:35		
Vendor Details :					
Company Name/Client Name :	Sotex India Pvt Ltd	Customer's Mobile :	9819049156	Name :	Shreeram Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	cannot view on tv				
Technician Comment :	new HDMI extender install and old remove and return office work completed				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	new HDMI extender install and old remove and return office work completed				

Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>23-01-2021 02:58:47</td><td>Ravi Rajbhar</td><td>Completed</td><td>new HDMI extender install and old remove and return office work completed</td><td></td></tr><tr><td>23-01-2021 02:42:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>23-01-2021 12:56:30</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>22-01-2021 04:37:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>18-01-2021 07:16:27</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>14-01-2021 10:08:46</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>14-01-2021 10:08:40</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>05-01-2021 02:58:39</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>new HDMI extender work ok in shriram sir cabin display off when switch near by cabin get on off and start working after some time</td><td></td></tr><tr><td>30-12-2020 10:14:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>05-12-2020 12:51:14</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>ther is issue in extender so collect for check it</td><td></td></tr><tr><td>03-12-2020 12:37:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>03-12-2020 12:37:35</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></table>	Date Time	Technician Name	Status	Remark	Sign	23-01-2021 02:58:47	Ravi Rajbhar	Completed	new HDMI extender install and old remove and return office work completed		23-01-2021 02:42:04	Ravi Rajbhar	New		-	23-01-2021 12:56:30	Ravi Rajbhar	New		-	22-01-2021 04:37:04	Ravi Rajbhar	New		-	18-01-2021 07:16:27	Ravi Rajbhar	New		-	14-01-2021 10:08:46	Ravi Rajbhar	New		-	14-01-2021 10:08:40	Ravi Rajbhar	New		-	05-01-2021 02:58:39	Ravi Rajbhar	Work Pending	new HDMI extender work ok in shriram sir cabin display off when switch near by cabin get on off and start working after some time		30-12-2020 10:14:04	Ravi Rajbhar	New		-	05-12-2020 12:51:14	Ravi Rajbhar	Work Pending	ther is issue in extender so collect for check it		03-12-2020 12:37:50	Ravi Rajbhar	New		-	03-12-2020 12:37:35	Ravi Rajbhar	New		-
	Date Time	Technician Name	Status	Remark	Sign																																																													
	23-01-2021 02:58:47	Ravi Rajbhar	Completed	new HDMI extender install and old remove and return office work completed																																																														
	23-01-2021 02:42:04	Ravi Rajbhar	New		-																																																													
	23-01-2021 12:56:30	Ravi Rajbhar	New		-																																																													
	22-01-2021 04:37:04	Ravi Rajbhar	New		-																																																													
	18-01-2021 07:16:27	Ravi Rajbhar	New		-																																																													
	14-01-2021 10:08:46	Ravi Rajbhar	New		-																																																													
	14-01-2021 10:08:40	Ravi Rajbhar	New		-																																																													
	05-01-2021 02:58:39	Ravi Rajbhar	Work Pending	new HDMI extender work ok in shriram sir cabin display off when switch near by cabin get on off and start working after some time																																																														
	30-12-2020 10:14:04	Ravi Rajbhar	New		-																																																													
	05-12-2020 12:51:14	Ravi Rajbhar	Work Pending	ther is issue in extender so collect for check it																																																														
	03-12-2020 12:37:50	Ravi Rajbhar	New		-																																																													
	03-12-2020 12:37:35	Ravi Rajbhar	New		-																																																													
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>29-07-2023 12:39:53</td><td>DilshadKhan</td><td></td></tr><tr><td>16-05-2023 10:15:05</td><td>Prashant Nikalje</td><td>prashant old visited site 16.05.2023 ivms not showing device offline change the network ashok sir laptop, smart office software install and configure given software training</td></tr></table>	Date Time	Technician Name	Remark	29-07-2023 12:39:53	DilshadKhan		16-05-2023 10:15:05	Prashant Nikalje	prashant old visited site 16.05.2023 ivms not showing device offline change the network ashok sir laptop, smart office software install and configure given software training																																																								
	Date Time	Technician Name	Remark																																																															
	29-07-2023 12:39:53	DilshadKhan																																																																
16-05-2023 10:15:05	Prashant Nikalje	prashant old visited site 16.05.2023 ivms not showing device offline change the network ashok sir laptop, smart office software install and configure given software training																																																																