

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13106															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9820858207														
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980											
Ticket Type :	Complain	Date & Time :	25-10-2024 12:47:46												
Vendor Details :															
Company Name/Client Name :	Net Technologies	Customer's Mobile :	9820858207	Name :	Shrenik Bhai										
Address :															
Mumbai , , , 400022 , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	Site: Ambernath - PTZ Camera off issue														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>28-10-2024 04:00:43</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	28-10-2024 04:00:43	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign											
28-10-2024 04:00:43	SantoshPathak	New		-											
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>26-10-2024 11:56:58</td><td>Sonu Kumar</td><td></td></tr><tr><td>10-10-2024 12:50:56</td><td>Sonu Kumar</td><td>2 bullet camera install all working ok and 1 dome camera collected</td></tr></table>					Date Time	Technician Name	Remark	26-10-2024 11:56:58	Sonu Kumar		10-10-2024 12:50:56	Sonu Kumar	2 bullet camera install all working ok and 1 dome camera collected	
Date Time	Technician Name	Remark													
26-10-2024 11:56:58	Sonu Kumar														
10-10-2024 12:50:56	Sonu Kumar	2 bullet camera install all working ok and 1 dome camera collected													