




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3970</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9867182981																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-10-2021 05:55:34																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Chheda Group (Parasnath Enterprises Builders & Developers	<b>Customer's Mobile :</b>	9867182981	<b>Name :</b>	Shweta																				
<b>Address :</b>																									
Mumbai , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	Access																								
<b>Complain :</b>	Lock issue																								
<b>Technician Comment :</b>	main gate lock issue resolved and working ok lock allingment done but door need to do speed slow .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	main gate lock issue resolved and working ok lock allingment done but door need to do speed slow .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-10-2021 07:01:52</td><td>Atique Salmani</td><td>Completed</td><td>main gate lock issue resolved and working ok lock allingment done but door need to do speed slow .</td><td></td></tr><tr><td>04-10-2021 05:55:58</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-10-2021 05:55:35</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-10-2021 07:01:52	Atique Salmani	Completed	main gate lock issue resolved and working ok lock allingment done but door need to do speed slow .		04-10-2021 05:55:58	Atique Salmani	New		-	04-10-2021 05:55:35	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-10-2021 07:01:52	Atique Salmani	Completed	main gate lock issue resolved and working ok lock allingment done but door need to do speed slow .																						
04-10-2021 05:55:58	Atique Salmani	New		-																					
04-10-2021 05:55:35	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-02-2022 06:54:15</td><td>Siddhesh Chavan</td><td>hdmi resolution change 1280*720/60HZ and tv view working ok and under observation</td></tr><tr><td>10-02-2022 10:41:48</td><td>Siddhesh Chavan</td><td>tajesh sir cabin no single issue resolved tv back side hdmi cable reconnect and tv view issue resolved and pankhil sir cabin tv view working ok and under observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-02-2022 06:54:15	Siddhesh Chavan	hdmi resolution change 1280*720/60HZ and tv view working ok and under observation	10-02-2022 10:41:48	Siddhesh Chavan	tajesh sir cabin no single issue resolved tv back side hdmi cable reconnect and tv view issue resolved and pankhil sir cabin tv view working ok and under observation											
Date Time	Technician Name	Remark																							
14-02-2022 06:54:15	Siddhesh Chavan	hdmi resolution change 1280*720/60HZ and tv view working ok and under observation																							
10-02-2022 10:41:48	Siddhesh Chavan	tajesh sir cabin no single issue resolved tv back side hdmi cable reconnect and tv view issue resolved and pankhil sir cabin tv view working ok and under observation																							