Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiablisecure@yali								
Service Status Det	ails : VE14865							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9820606496							
Technician Name :	Siddhesh Chavan			Technician Mobile :		8080922985		
Ticket Type :	Complain 1	Date & Time :	3	30-05-2025 10:	31:42)		
Vendor Details :	-							
Company Name/Client Name :		Customer's Mobile :		9820606496		Name :	Siddhivinayak Sra Skylone	
Address:								
Mumbai , , , , Mah	arashtra							
AMC Details :								
Expiry Date :	01-01-1970 05:30:	:00	Т	Type:				
Product Name:	CCTV							
Complain:	In Monitor not able to check cameras							
Technician Comment :	Monitor issue need change and lift camera issue arrange lift person and 2camera office issue pending and one camera need sift							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	Monitor issue need change and lift camera issue arrange lift person and 2camera office issue pending and one camera need sift							
Status History :	Date Time	Technician Name		Status		Remark		Sign
	30-05-2025 12:24:42	Siddhesh Chavan		Work Pending	and arra 2ca pen	Monitor issue need changand lift camera issue arrange lift person and 2camera office issue pending and one camera need sift		popula
	30-05-2025 10:31:48	Siddhesh Chavan		New				-
Previous Complain History:	Date Time	Technician Name		Remark				
	14-07-2025 11:46:59	Atique Salmani	ter	3 rd lift issue resolved main power supply was off from db And terrace 2 cameras new cabling approx 305 metr and poe switch en all connector need to changed				
	06-03-2025 12:32:34	Neeraj Chauhan	Terrance 2 camera cable damaged on fire ?????????? new cabling requirement aprox 300-350 mtr 3 no life camera working but switch side no Link cable and access point checking life person required ground floor lift Side camera shifting to stare cash out side camera broken damage cricket ball new camera requirement and bilding out side 2 camera shifting required camera live in mobile on society person					