Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails : VE15259							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	9820606496							
Technician Name :	Atique Salmani		Technicia: Mobile :	n 808092298		34		
Ticket Type:	Complain Date & Time :		14-07-2025 11:46:59)			
Vendor Details :								
Company Name/Client Name :	Customer's Mobile :		9820606496		Name:	Siddhivinayak Sra Skylone		
Address:								
Mumbai , , , , Ma	harashtra							
AMC Details :								
Expiry Date :	01-01-1970 05:30	Type:						
Product Name:	CCTV							
Complain:	lift 1 camera off issue							
Technician Comment :	3 rd lift issue resolved main power supply was off from db And terrace 2 cameras new cabling approx 305 metr and poe switch en all connector need to changed							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	3 rd lift issue resolved main power supply was off from db And terrace 2 cameras new cabling approx 305 metr and poe switch en all connector need to changed							
Status History :	Date Time	Technician Name	Status	Remark		Sign		
	14-07-2025 04:48:51	Atique Salmani	Completed	3 rd lift issue resolved main power supply was off from db And terrace 2 cameras new cabling approx 305 metr and poe switch en all connector need to changed		Rakerh		
	14-07-2025 04:48:51	Atique Salmani	Completed	supply wa 2 cameras metr and	sue resolved main is off from db And is new cabling app poe switch en all r need to changed	terrace rox 305	Rakerh	
	14-07-2025 11:47:18	Atique Salmani	New				-	

Previous Complain History :	Date Time	Technician Name	Remark	
	30-05-2025 10:31:42	Siddhesh Chavan	Monitor issue need change and lift camera issue arrange lift person and 2camera office issue pending and one camera need sift	
	06-03-2025 12:32:34	Neeraj Chauhan	Terrance 2 camera cable damaged on fire ??????????? new cabling requirement aprox 300-350 mtr 3 no life camera working but switch side no Link cable and access point checking life person required ground floor lift Side camera shifting to stare cash out side camera broken damage cricket ball new camera requirement and bilding out side 2 camera shifting required camera live in mobile on society person	