

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14653															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	8169342474														
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949											
Ticket Type :	Complain	Date & Time :	03-05-2025 10:38:15												
Vendor Details :															
Company Name/Client Name :	Mahavir Kalpavruksh J Wing - Orchid Bldg	Customer's Mobile :	8169342474	Name :	Singh Sir										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	VDP														
Complain :	some flats programming issue need to check														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-05-2025 10:39:57</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-05-2025 10:39:57	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign											
03-05-2025 10:39:57	Rahul Mhapralkar	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-05-2025 05:07:12</td><td>Rahul Mhapralkar</td><td>Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.</td></tr><tr><td>12-05-2025 05:32:02</td><td>Rahul Mhapralkar</td><td>3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-05-2025 05:07:12	Rahul Mhapralkar	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.	12-05-2025 05:32:02	Rahul Mhapralkar	3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available	
Date Time	Technician Name	Remark													
23-05-2025 05:07:12	Rahul Mhapralkar	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.													
12-05-2025 05:32:02	Rahul Mhapralkar	3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available													