







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14806																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8169342474																								
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																					
Ticket Type :	Complain	Date & Time :	23-05-2025 05:07:12																						
Vendor Details :																									
Company Name/Client Name :	Mahavir Kalpavruksh J Wing - Orchid Bldg	Customer's Mobile :	8169342474	Name :	Singh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	Flat no 2306 Showing error query failed - 9819689012																								
Technician Comment :	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-05-2025 05:23:56</td><td>Rahul Mhapralkar</td><td>Completed</td><td>Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.</td><td></td></tr><tr><td>23-05-2025 05:23:55</td><td>Rahul Mhapralkar</td><td>Completed</td><td>Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.</td><td></td></tr><tr><td>23-05-2025 05:07:17</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-05-2025 05:23:56	Rahul Mhapralkar	Completed	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.		23-05-2025 05:23:55	Rahul Mhapralkar	Completed	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.		23-05-2025 05:07:17	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-05-2025 05:23:56	Rahul Mhapralkar	Completed	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.																						
23-05-2025 05:23:55	Rahul Mhapralkar	Completed	Indoor monitor viewing issue screen reset and reprogram and problem now resolved working normally.																						
23-05-2025 05:07:17	Rahul Mhapralkar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-05-2025 05:32:02</td><td>Rahul Mhapralkar</td><td>3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available</td></tr><tr><td>03-05-2025 10:38:15</td><td>Rahul Mhapralkar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	12-05-2025 05:32:02	Rahul Mhapralkar	3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available	03-05-2025 10:38:15	Rahul Mhapralkar												
Date Time	Technician Name	Remark																							
12-05-2025 05:32:02	Rahul Mhapralkar	3207 IP Conflict issue resolved and 1912 crimping done proper issue resolved 606 customer not available																							
03-05-2025 10:38:15	Rahul Mhapralkar																								