

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
 Support : | W : www.vallabhenterprises.com  
 E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11719</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9820612503																			
<b>Technician Name :</b>	Neeraj Chauhan	<b>Technician Mobile :</b>	8898885764																	
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	24-05-2024 10:34:31																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Saikripa Auto And Oil Center	<b>Customer's Mobile :</b>	9820612503	<b>Name :</b>	Subhash Sir															
<b>Address :</b>																				
Mumbai , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00	<b>Type :</b>																		
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	Rack fan/camera housing and USB Cable need to install																			
<b>Technician Comment :</b>	1 bullet camera and camera housing installation and 2 camera angle set dvr exception issue solve usb extension install 10 mtr 2 nos Rack Fan install Ac/Dc																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	1 bullet camera and camera housing installation and 2 camera angle set dvr exception issue solve usb extension install 10 mtr 2 nos Rack Fan install Ac/Dc																			
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>24-05-2024 04:40:06</td> <td>Neeraj Chauhan</td> <td>Completed</td> <td>1 bullet camera and camera housing installation and 2 camera angle set dvr exception issue solve usb extension install 10 mtr 2 nos Rack Fan install Ac/Dc</td> <td></td> </tr> <tr> <td>24-05-2024 10:34:38</td> <td>Neeraj Chauhan</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	24-05-2024 04:40:06	Neeraj Chauhan	Completed	1 bullet camera and camera housing installation and 2 camera angle set dvr exception issue solve usb extension install 10 mtr 2 nos Rack Fan install Ac/Dc		24-05-2024 10:34:38	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-05-2024 04:40:06	Neeraj Chauhan	Completed	1 bullet camera and camera housing installation and 2 camera angle set dvr exception issue solve usb extension install 10 mtr 2 nos Rack Fan install Ac/Dc																	
24-05-2024 10:34:38	Neeraj Chauhan	New		-																
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>24-05-2024 05:10:55</td> <td>Neeraj Chauhan</td> <td>3 camera no video issue solve and camera working okk</td> </tr> <tr> <td>10-05-2024 10:48:23</td> <td>Neeraj Chauhan</td> <td>CNG pump ppm done dvr cleaning and all camera cleaning nvr nvr Rack monitor some camera complaint solve</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	24-05-2024 05:10:55	Neeraj Chauhan	3 camera no video issue solve and camera working okk	10-05-2024 10:48:23	Neeraj Chauhan	CNG pump ppm done dvr cleaning and all camera cleaning nvr nvr Rack monitor some camera complaint solve						
Date Time	Technician Name	Remark																		
24-05-2024 05:10:55	Neeraj Chauhan	3 camera no video issue solve and camera working okk																		
10-05-2024 10:48:23	Neeraj Chauhan	CNG pump ppm done dvr cleaning and all camera cleaning nvr nvr Rack monitor some camera complaint solve																		