




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE14520</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820577881																													
<b>Technician Name :</b>	Neeraj Chauhan		<b>Technician Mobile :</b>	8898885764																										
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	18-04-2025 10:18:31																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	LIFT CAMERA NEED TO INSTALL																													
<b>Technician Comment :</b>	2 life survey done and total cabling length 220 MTR Old cuting on celing work																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	2 life survey done and total cabling length 220 MTR Old cuting on celing work																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-04-2025 01:02:04</td><td>Neeraj Chauhan</td><td>Completed</td><td>2 life survey done and total cabling length 220 MTR Old cuting on celing work</td><td></td></tr><tr><td>22-04-2025 10:37:40</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-04-2025 10:22:56</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>18-04-2025 10:18:54</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-04-2025 01:02:04	Neeraj Chauhan	Completed	2 life survey done and total cabling length 220 MTR Old cuting on celing work		22-04-2025 10:37:40	Neeraj Chauhan	New		-	21-04-2025 10:22:56	Neeraj Chauhan	New		-	18-04-2025 10:18:54	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
22-04-2025 01:02:04	Neeraj Chauhan	Completed	2 life survey done and total cabling length 220 MTR Old cuting on celing work																											
22-04-2025 10:37:40	Neeraj Chauhan	New		-																										
21-04-2025 10:22:56	Neeraj Chauhan	New		-																										
18-04-2025 10:18:54	Neeraj Chauhan	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-07-2025 11:25:52</td><td>PravinJagade</td><td>In lift 2 phone installation done</td></tr><tr><td>30-06-2025 03:03:51</td><td>Atique Salmani</td><td>Lift cabling done with 15 cameras on with recording medical side old cable pair issue temporary on and all cameras dvr reinstalled and also tv installation done all working ok 2 nos lift instrument need to changed .</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-07-2025 11:25:52	PravinJagade	In lift 2 phone installation done	30-06-2025 03:03:51	Atique Salmani	Lift cabling done with 15 cameras on with recording medical side old cable pair issue temporary on and all cameras dvr reinstalled and also tv installation done all working ok 2 nos lift instrument need to changed .																
Date Time	Technician Name	Remark																												
04-07-2025 11:25:52	PravinJagade	In lift 2 phone installation done																												
30-06-2025 03:03:51	Atique Salmani	Lift cabling done with 15 cameras on with recording medical side old cable pair issue temporary on and all cameras dvr reinstalled and also tv installation done all working ok 2 nos lift instrument need to changed .																												