




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1536																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820577881																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	09-07-2020 12:15:03																						
Vendor Details :																									
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	intercom issue																								
Technician Comment :	check all flats intercom 601 instruments issue 901 line was dead check n resolved issue and also boath lifts check working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	check all flats intercom 601 instruments issue 901 line was dead check n resolved issue and also boath lifts check working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-07-2020 02:48:21</td><td>Atique Salmani</td><td>Completed</td><td>check all flats intercom 601 instruments issue 901 line was dead check n resolved issue and also boath lifts check working ok.</td><td></td></tr><tr><td>10-07-2020 11:36:07</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>09-07-2020 12:15:04</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-07-2020 02:48:21	Atique Salmani	Completed	check all flats intercom 601 instruments issue 901 line was dead check n resolved issue and also boath lifts check working ok.		10-07-2020 11:36:07	Atique Salmani	New		-	09-07-2020 12:15:04	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-07-2020 02:48:21	Atique Salmani	Completed	check all flats intercom 601 instruments issue 901 line was dead check n resolved issue and also boath lifts check working ok.																						
10-07-2020 11:36:07	Atique Salmani	New		-																					
09-07-2020 12:15:04	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 01:25:15</td><td>Ravi Rajbhar</td><td>202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23</td></tr><tr><td>20-07-2023 01:23:14</td><td>Kalpesh SubhashGurav</td><td>Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23	20-07-2023 01:23:14	Kalpesh SubhashGurav	Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset											
Date Time	Technician Name	Remark																							
29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																							
20-07-2023 01:23:14	Kalpesh SubhashGurav	Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset																							