

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2839																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820577881																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	15-03-2021 10:39:23																						
Vendor Details :																									
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	3-4 flats intercom issue																								
Technician Comment :	1002 line ok instrument issue 701 door lock 702 line ok instrument issue(new phone install and cash collat 550) 703 line ok instrument issue(new phone install and crash collat 5050) 501 ok 403 ok																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1002 line ok instrument issue 701 door lock 702 line ok instrument issue(new phone install and cash collat 550) 703 line ok instrument issue(new phone install and crash collat 5050) 501 ok 403 ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-03-2021 12:59:09</td><td>Ravi Rajbhar</td><td>Completed</td><td>1002 line ok instrument issue 701 door lock 702 line ok instrument issue(new phone install and cash collat 550) 703 line ok instrument issue(new phone install and crash collat 5050) 501 ok 403 ok</td><td></td></tr><tr><td>15-03-2021 10:39:36</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>15-03-2021 10:39:23</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-03-2021 12:59:09	Ravi Rajbhar	Completed	1002 line ok instrument issue 701 door lock 702 line ok instrument issue(new phone install and cash collat 550) 703 line ok instrument issue(new phone install and crash collat 5050) 501 ok 403 ok		15-03-2021 10:39:36	Ravi Rajbhar	New		-	15-03-2021 10:39:23	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
15-03-2021 12:59:09	Ravi Rajbhar	Completed	1002 line ok instrument issue 701 door lock 702 line ok instrument issue(new phone install and cash collat 550) 703 line ok instrument issue(new phone install and crash collat 5050) 501 ok 403 ok																						
15-03-2021 10:39:36	Ravi Rajbhar	New		-																					
15-03-2021 10:39:23	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-08-2023 11:09:33</td><td>ChandanYadav</td><td>303 intercom complain solve and 2 camera angle sitting.</td></tr><tr><td>29-07-2023 01:25:15</td><td>Ravi Rajbhar</td><td>202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.	29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23											
Date Time	Technician Name	Remark																							
07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.																							
29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																							

