

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3651																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9820577881																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	16-08-2021 02:31:30																											
Vendor Details :																														
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Intercom																													
Complain :	intercom issue																													
Technician Comment :	301 .602 301 intercom issue resolved reconnection from lobby pannel and working ok.602 lock no one at home .																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	301 .602 301 intercom issue resolved reconnection from lobby pannel and working ok.602 lock no one at home .																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-08-2021 02:47:03</td><td>Atique Salmani</td><td>Completed</td><td>301 .602 301 intercom issue resolved reconnection from lobby pannel and working ok.602 lock no one at home .</td><td></td></tr><tr><td>17-08-2021 12:36:36</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>16-08-2021 02:32:06</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>16-08-2021 02:31:30</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-08-2021 02:47:03	Atique Salmani	Completed	301 .602 301 intercom issue resolved reconnection from lobby pannel and working ok.602 lock no one at home .		17-08-2021 12:36:36	Atique Salmani	New		-	16-08-2021 02:32:06	Atique Salmani	New		-	16-08-2021 02:31:30	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
17-08-2021 02:47:03	Atique Salmani	Completed	301 .602 301 intercom issue resolved reconnection from lobby pannel and working ok.602 lock no one at home .																											
17-08-2021 12:36:36	Atique Salmani	New		-																										
16-08-2021 02:32:06	Atique Salmani	New		-																										
16-08-2021 02:31:30	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-08-2023 11:09:33</td><td>ChandanYadav</td><td>303 intercom complain solve and 2 camera angle sitting.</td></tr><tr><td>29-07-2023 01:25:15</td><td>Ravi Rajbhar</td><td>202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.	29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																
Date Time	Technician Name	Remark																												
07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.																												
29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																												