




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4286</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820577881																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	27-11-2021 10:02:41																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	security phone issue																								
<b>Technician Comment :</b>	Security intercom issue sloved new intercom had been installed. flat no 201 - intercom issue need to change. flat no 401, & 901 two rj 21 used phone disturbance sloved.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Security intercom issue sloved new intercom had been installed. flat no 201 - intercom issue need to change. flat no 401, & 901 two rj 21 used phone disturbance sloved.																								
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>27-11-2021 02:46:11</td> <td>YogeshDesai</td> <td>Completed</td> <td>Security intercom issue sloved new intercom had been installed. flat no 201 - intercom issue need to change. flat no 401, &amp; 901 two rj 21 used phone disturbance sloved.</td> <td></td> </tr> <tr> <td>27-11-2021 10:02:54</td> <td>YogeshDesai</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>27-11-2021 10:02:41</td> <td>YogeshDesai</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	27-11-2021 02:46:11	YogeshDesai	Completed	Security intercom issue sloved new intercom had been installed. flat no 201 - intercom issue need to change. flat no 401, & 901 two rj 21 used phone disturbance sloved.		27-11-2021 10:02:54	YogeshDesai	New		-	27-11-2021 10:02:41	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
27-11-2021 02:46:11	YogeshDesai	Completed	Security intercom issue sloved new intercom had been installed. flat no 201 - intercom issue need to change. flat no 401, & 901 two rj 21 used phone disturbance sloved.																						
27-11-2021 10:02:54	YogeshDesai	New		-																					
27-11-2021 10:02:41	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>12-02-2022 05:03:09</td> <td>Atique Salmani</td> <td>ppm done 402 ringing issue solve and 1001 lock ppm done cctv make check list .</td> </tr> <tr> <td>29-01-2022 02:37:04</td> <td>Ravi Rajbhar</td> <td>703, 601, 603 , intercom issue resolved and ok working done door lock 201,203,902</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	12-02-2022 05:03:09	Atique Salmani	ppm done 402 ringing issue solve and 1001 lock ppm done cctv make check list .	29-01-2022 02:37:04	Ravi Rajbhar	703, 601, 603 , intercom issue resolved and ok working done door lock 201,203,902											
Date Time	Technician Name	Remark																							
12-02-2022 05:03:09	Atique Salmani	ppm done 402 ringing issue solve and 1001 lock ppm done cctv make check list .																							
29-01-2022 02:37:04	Ravi Rajbhar	703, 601, 603 , intercom issue resolved and ok working done door lock 201,203,902																							