

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14777																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9137770968																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	21-05-2025 11:13:21																	
Vendor Details :																				
Company Name/Client Name :	Mandar Pushpa	Customer's Mobile :	9137770968	Name :	Sujata Madam															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-06-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Flat no 403 video door phone is not working																			
Technician Comment :	video door phone issue resolved and ok working done seen side connector issue and then connector propley connect seen																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	video door phone issue resolved and ok working done seen side connector issue and then connector propley connect seen																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-05-2025 01:13:40</td><td>Ravi Rajbhar</td><td>Completed</td><td>video door phone issue resolved and ok working done seen side connector issue and then connector propley connect seen</td><td></td></tr><tr><td>21-05-2025 11:13:29</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-05-2025 01:13:40	Ravi Rajbhar	Completed	video door phone issue resolved and ok working done seen side connector issue and then connector propley connect seen		21-05-2025 11:13:29	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
21-05-2025 01:13:40	Ravi Rajbhar	Completed	video door phone issue resolved and ok working done seen side connector issue and then connector propley connect seen																	
21-05-2025 11:13:29	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-03-2025 10:46:21</td><td>Neeraj Chauhan</td><td>501 indoor new screen installation done and out door unit reinstall didong bell PCB not working 7500 gp collect</td></tr><tr><td>13-01-2025 05:23:23</td><td>Siddhesh Chavan</td><td>New lobby panel install done and calling working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-03-2025 10:46:21	Neeraj Chauhan	501 indoor new screen installation done and out door unit reinstall didong bell PCB not working 7500 gp collect	13-01-2025 05:23:23	Siddhesh Chavan	New lobby panel install done and calling working ok						
Date Time	Technician Name	Remark																		
31-03-2025 10:46:21	Neeraj Chauhan	501 indoor new screen installation done and out door unit reinstall didong bell PCB not working 7500 gp collect																		
13-01-2025 05:23:23	Siddhesh Chavan	New lobby panel install done and calling working ok																		