







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5293</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9819867895																																		
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	26-04-2022 09:58:35																																
<b>Vendor Details :</b>																																			
<b>Company Name/Client Name :</b>	Dhavalgiri Co Op Hsg Society Limited	<b>Customer's Mobile :</b>	9819867895	<b>Name :</b>	Suresh Sir																														
<b>Address :</b>																																			
Mumbai , , , 400068 , Maharashtra																																			
<b>AMC Details :</b>																																			
<b>Expiry Date :</b>	30-06-2021 12:00:00		<b>Type :</b>	Comprehensive																															
<b>Product Name :</b>	CCTV																																		
<b>Complain :</b>	2 bullet camera need to change																																		
<b>Technician Comment :</b>	one new bullet camera install and working ok																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	one new bullet camera install and working ok																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-05-2022 04:09:22</td><td>Siddhesh Chavan</td><td>Completed</td><td>one new bullet camera install and working ok</td><td></td></tr><tr><td>10-05-2022 04:07:11</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>26-04-2022 11:32:35</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>one camera change and old camera take to office and one camera issue pending</td><td></td></tr><tr><td>26-04-2022 09:58:50</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>26-04-2022 09:58:35</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-05-2022 04:09:22	Siddhesh Chavan	Completed	one new bullet camera install and working ok		10-05-2022 04:07:11	Siddhesh Chavan	New		-	26-04-2022 11:32:35	Siddhesh Chavan	Work Pending	one camera change and old camera take to office and one camera issue pending		26-04-2022 09:58:50	Siddhesh Chavan	New		-	26-04-2022 09:58:35	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
10-05-2022 04:09:22	Siddhesh Chavan	Completed	one new bullet camera install and working ok																																
10-05-2022 04:07:11	Siddhesh Chavan	New		-																															
26-04-2022 11:32:35	Siddhesh Chavan	Work Pending	one camera change and old camera take to office and one camera issue pending																																
26-04-2022 09:58:50	Siddhesh Chavan	New		-																															
26-04-2022 09:58:35	Siddhesh Chavan	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-04-2022 10:08:29</td><td>Atique Salmani</td><td>ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .</td></tr><tr><td>16-01-2022 10:55:25</td><td>Atique Salmani</td><td>all cameras cleaned and also dvr clean make check list of dvr all working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-04-2022 10:08:29	Atique Salmani	ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .	16-01-2022 10:55:25	Atique Salmani	all cameras cleaned and also dvr clean make check list of dvr all working ok.																					
Date Time	Technician Name	Remark																																	
22-04-2022 10:08:29	Atique Salmani	ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .																																	
16-01-2022 10:55:25	Atique Salmani	all cameras cleaned and also dvr clean make check list of dvr all working ok.																																	