Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE8494							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9821919559						
Technician Name	Sonu Kumar		Technici	cian Mobile 8454016444			
Ticket Type:	Complain	Date & Time :	05-06-20	05-06-2023 10:15:14			
Vendor Details :							
Company Name/Client Name :	Rahul International School - Boisar	Customer's Mobil :	e 9821919	9821919559		Sushil Sir - Boisar	
Address:							
Mumbai , boisar WEST , , 401501 , Maharashtra							
AMC Details:							
Expiry Date :	01-01-1970 05:30:00	Type:	Type:				
Product Name:	CCTV						
Complain:	Back gate office 2 cameras not working						
Technician Comment :	Back gate 2 camera off issue resolved working ok 1 pair video ballons used and User name admin Password						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Back gate 2 camera off issue resolved working ok 1 pair video ballons used and User name admin Password						
Status History:	Date Time	Technician Name	Status	Remark Back gate 2 camera off issue resolved working ok 1 pair video ballons used and User name admin Password		Sign	
	05-06-2023 02:57:44	Sonu Kumar	Completed			Mka	
	05-06-2023 10:16:02	Sonu Kumar	New			-	
Previous Complain History :	Date Time	Technician Name		Remark			
	02-05-2023 11:03:34	Ishwar Meena	1st Floor room	(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace			
	20-03-2023 10:33:28	PravinJagade		nd floor dvr beep sound issue resolve. Beep sound off. setting change. Hdd normal working done. All camera ing.			