

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12987																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9769755007																			
Technician Name :	Manoj Polekar		Technician Mobile :	7385366458																
Ticket Type :	Complain	Date & Time :	15-10-2024 10:58:15																	
Vendor Details :																				
Company Name/Client Name :	Rahul Degree Collage Miraroad	Customer's Mobile :	9769755007	Name :	Sushil Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Old Bldg 3rd floor passage 1 camera flickering issue																			
Technician Comment :	1 camera flickering issue resolved 1 DC change																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1 camera flickering issue resolved 1 DC change																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-10-2024 01:20:06</td><td>ManojPolekar</td><td>Completed</td><td>1 camera flickering issue resolved 1 DC change</td><td></td></tr><tr><td>15-10-2024 06:55:57</td><td>ManojPolekar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-10-2024 01:20:06	ManojPolekar	Completed	1 camera flickering issue resolved 1 DC change		15-10-2024 06:55:57	ManojPolekar	New		-
Date Time	Technician Name	Status	Remark	Sign																
16-10-2024 01:20:06	ManojPolekar	Completed	1 camera flickering issue resolved 1 DC change																	
15-10-2024 06:55:57	ManojPolekar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-08-2024 12:31:26</td><td>Shiva Meena</td><td>Class no. 103 and 106 new camera installation done</td></tr><tr><td>28-08-2024 10:47:57</td><td>Atique Salmani</td><td>C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-08-2024 12:31:26	Shiva Meena	Class no. 103 and 106 new camera installation done	28-08-2024 10:47:57	Atique Salmani	C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .						
Date Time	Technician Name	Remark																		
31-08-2024 12:31:26	Shiva Meena	Class no. 103 and 106 new camera installation done																		
28-08-2024 10:47:57	Atique Salmani	C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .																		