

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2874																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9773740406																																		
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																															
Ticket Type :	Complain	Date & Time :	22-03-2021 09:52:52																																
Vendor Details :																																			
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir																														
Address :																																			
Mumbai , , , 400064 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																															
Product Name :	CCTV																																		
Complain :	lift camera issue and intercom issue																																		
Technician Comment :																																			
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :																																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-08-2023 01:26:13</td><td>Siddhesh Chavan</td><td>Completed</td><td></td><td>-</td></tr><tr><td>22-03-2021 06:03:06</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-03-2021 04:36:29</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-03-2021 09:53:06</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-03-2021 09:52:52</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-08-2023 01:26:13	Siddhesh Chavan	Completed		-	22-03-2021 06:03:06	Siddhesh Chavan	New		-	22-03-2021 04:36:29	Siddhesh Chavan	New		-	22-03-2021 09:53:06	Siddhesh Chavan	New		-	22-03-2021 09:52:52	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
02-08-2023 01:26:13	Siddhesh Chavan	Completed		-																															
22-03-2021 06:03:06	Siddhesh Chavan	New		-																															
22-03-2021 04:36:29	Siddhesh Chavan	New		-																															
22-03-2021 09:53:06	Siddhesh Chavan	New		-																															
22-03-2021 09:52:52	Siddhesh Chavan	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:33:52</td><td>Ravi Rajbhar</td><td>two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending</td></tr><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending	15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																					
Date Time	Technician Name	Remark																																	
31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending																																	
15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																																	