

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3128																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9773740406																																							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																																				
Ticket Type :	Complain	Date & Time :	24-05-2021 05:02:45																																					
Vendor Details :																																								
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir																																			
Address :																																								
Mumbai , , , 400064 , Maharashtra																																								
AMC Details :																																								
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																																				
Product Name :	VDP																																							
Complain :	lobo sir flat vdp issue																																							
Technician Comment :																																								
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :																																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-05-2021 05:02:32</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>25-05-2021 12:34:49</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>24-05-2021 06:32:22</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>24-05-2021 05:34:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>24-05-2021 05:02:57</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>24-05-2021 05:02:45</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-05-2021 05:02:32	Ravi Rajbhar	New		-	25-05-2021 12:34:49	Ravi Rajbhar	New		-	24-05-2021 06:32:22	Ravi Rajbhar	New		-	24-05-2021 05:34:14	Ravi Rajbhar	New		-	24-05-2021 05:02:57	Ravi Rajbhar	New		-	24-05-2021 05:02:45	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
26-05-2021 05:02:32	Ravi Rajbhar	New		-																																				
25-05-2021 12:34:49	Ravi Rajbhar	New		-																																				
24-05-2021 06:32:22	Ravi Rajbhar	New		-																																				
24-05-2021 05:34:14	Ravi Rajbhar	New		-																																				
24-05-2021 05:02:57	Ravi Rajbhar	New		-																																				
24-05-2021 05:02:45	Ravi Rajbhar	New		-																																				
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:33:52</td><td>Ravi Rajbhar</td><td>two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with connectoin pending</td></tr><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with connectoin pending	15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																										
Date Time	Technician Name	Remark																																						
31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with connectoin pending																																						
15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																																						