

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4810																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9773740406																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	17-02-2022 02:44:24																						
Vendor Details :																									
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir																				
Address :																									
Mumbai , , , 400064 , Maharashtra																									
AMC Details :																									
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	Intercom																								
Complain :	flat no 1502 intercom not working																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :																									
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-02-2022 10:29:27</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>17-02-2022 02:44:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>17-02-2022 02:44:24</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-02-2022 10:29:27	Ravi Rajbhar	New		-	17-02-2022 02:44:50	Ravi Rajbhar	New		-	17-02-2022 02:44:24	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
18-02-2022 10:29:27	Ravi Rajbhar	New		-																					
17-02-2022 02:44:50	Ravi Rajbhar	New		-																					
17-02-2022 02:44:24	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:33:52</td><td>Ravi Rajbhar</td><td>two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wrking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending</td></tr><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wrking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending	15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.											
Date Time	Technician Name	Remark																							
31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wrking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending																							
15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																							