Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vallabhsecure@yahoo.co.in							
Service Status Det	ails: VE11963						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9922942248						
Technician Name:	Atique Salmani		Technici	ian Mobile 8080922984			
Ticket Type :	New Installation	Date & Time :	22-06-20	2-06-2024 11:58:09			
Vendor Details :							
Company Name/Client Name :	Brookhil Chs	Customer's Mobile:	e 9922942	248	Name :	Swati Mam	
Address:							
Mumbai , , , , Mah	arashtra						
AMC Details:							
Expiry Date :	01-01-1970 05:30:00		Type:				
Product Name:	Ppm						
Complain :	1 camera no video issue and in few cameras naming need to do and CCTV/Intercom/Access PPM need to do						
Technician Comment :	All cameras lence cleaning done and one camera issue resolved. And also all intercom working and 4 door access working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	All cameras lence cleaning done and one camera issue resolved. And also all intercom working and $4\ door\ access$ working ok.						
Status History :	Date Time	Technician Name	Status	Remark Sign All cameras lence cleaning done and one camera issue resolved. And also all intercom working and 4 door access working ok.		Sign	
	22-06-2024 03:36:21	Atique Salmani	Completed			1	
	22-06-2024 11:58:19	Atique Salmani	New			-	
Previous	Date Time	Technician Name		Remark			
Complain History :	25-06-2024 10:28:11	Atique Salmani	Power consumption so lift camera become off and now it's working ok and 2401 intercom issue resolved by from duct side cable issue so swap cable and working ok and basement exit switch issue sonthere is asmall swich in sapare so use that switch working ok but need big size swich in next visit all cctv working ok.				
	08-06-2024 11:06:09	Neeraj Chauhan	System under	System under objarvation			