Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE12044 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9922942248 **No. : Technician Name** Rahul Mhapralkar **Technician Mobile :** 9168762949 Complain 02-07-2024 04:36:17 **Ticket Type : Date & Time :** Vendor Details : Brookhil Chs Customer's Mobile : 9922942248 Swati Mam Company Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: not able to see recording Society room cctv access done and recording visible on device, camera name changes, Now Technician **Comment** : working Normally. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Society room cctv access done and recording visible on device, camera name changes, Now working Normally. **Status History : Date Time Technician Name** Status Remark Sign 04-07-2024 12:57:50 Rahul Mhapralkar Completed Society room cctv access done and recording visible on device, camera name changes, Now working Normally. 04-07-2024 10:40:42 Rahul Mhapralkar New 03-07-2024 10:14:50 Rahul Mhapralkar New Previous Technician **Complain History Date Time** Remark Name 26-06-2024 03:37:32 25-06-2024 10:28:11 Atique Salmani Power consumption so lift camera become off and now it's working ok and 2401 intercom issue resolved by from duct side cable issue so swap cable and working ok and basement exit switch issue sonthere is asmall swich in sapare so use that switch working ok but need big size swich in next visit all cctv working ok.