

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13986																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9922942248																													
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																										
Ticket Type :	Complain	Date & Time :	01-02-2025 10:10:50																											
Vendor Details :																														
Company Name/Client Name :	Brookhil Chs	Customer's Mobile :	9922942248	Name :	Swati Mam																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	16th floor NVR beep sound issue																													
Technician Comment :	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-02-2025 12:38:58</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr><tr><td>01-02-2025 11:13:31</td><td>Rahul Mhapralkar</td><td>Work Pending</td><td>16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change</td><td></td></tr><tr><td>01-02-2025 11:13:29</td><td>Rahul Mhapralkar</td><td>Work Pending</td><td>16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change</td><td></td></tr><tr><td>01-02-2025 10:11:04</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-02-2025 12:38:58	Rahul Mhapralkar	New		-	01-02-2025 11:13:31	Rahul Mhapralkar	Work Pending	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change		01-02-2025 11:13:29	Rahul Mhapralkar	Work Pending	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change		01-02-2025 10:11:04	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
10-02-2025 12:38:58	Rahul Mhapralkar	New		-																										
01-02-2025 11:13:31	Rahul Mhapralkar	Work Pending	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change																											
01-02-2025 11:13:29	Rahul Mhapralkar	Work Pending	16 floor NVR beep sound issue resolved, 11th floor camera offline joineder need to change																											
01-02-2025 10:11:04	Rahul Mhapralkar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-05-2025 10:56:14</td><td>TauseephRaza</td><td>Door lock work ok</td></tr><tr><td>14-04-2025 11:04:36</td><td>Atique Salmani</td><td>Main gate intercom issue resolved 2205 intercom issue resolved Reception telephone instrument issue. Lift cameras TV monitor issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-05-2025 10:56:14	TauseephRaza	Door lock work ok	14-04-2025 11:04:36	Atique Salmani	Main gate intercom issue resolved 2205 intercom issue resolved Reception telephone instrument issue. Lift cameras TV monitor issue																
Date Time	Technician Name	Remark																												
07-05-2025 10:56:14	TauseephRaza	Door lock work ok																												
14-04-2025 11:04:36	Atique Salmani	Main gate intercom issue resolved 2205 intercom issue resolved Reception telephone instrument issue. Lift cameras TV monitor issue																												