Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE14434 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9922942248 **No. : Technician** Chandan Yadav **Technician Mobile :** 9833262842 Name : Complain 07-04-2025 10:53:08 **Ticket Type :** Date & Time : **Vendor Details :** Brookhil Chs Customer's Mobile : 9922942248 Swati Mam Company Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** cCTV-Intercom **Complain**: CCTV issue and intercom of reception and main gate are not working properly main gate intercom pending out side two camera not working and only main gate camera not **Technician Comment** : working, work in progress on the building. Three camera not working. The cable was cut due to a falling rock. 200 mtr cakble lagega. Complain Desktop - Apurva Vajaria **Operator** : main gate intercom pending out side two camera not working and only main gate camera not **Remark** : working, work in progress on the building. Three camera not working. The cable was cut due to a falling rock. 200 mtr cakble lagega. **Status History : Date Time Technician Name** Status Remark Sign 07-04-2025 ChandanYaday Client main gate intercom pending out side 11:55:16 Side two camera not working and only R main gate camera not working. work in progress on the building. Three camera not working. The cable was cut due to a falling rock. 200 mtr cakble lagega. 07-04-2025 ChandanYadav New 10:54:08 **Previous Date Time Technician Name** Remark Complain **History** : 07-05-2025 10:56:14 TauseephRaza Door lock work ok 14-04-2025 11:04:36 Atique Salmani Main gate intercom issue resolved 2205 intercom issue resolved Reception telephone instrument issue. Lift cameras TV monitor issue