




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1364</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9821013634																								
<b>Technician Name :</b>	Sachin Pawar		<b>Technician Mobile :</b>	8080922981																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	12-03-2020 03:45:48																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	T B Patel-Home	<b>Customer's Mobile :</b>	9821013634	<b>Name :</b>	T B Patel																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	beep sound in dvr																								
<b>Technician Comment :</b>	dvr power adapter is faulty so selft supply installed as observation as disscussed with apyrva sir																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	dvr power adapter is faulty so selft supply installed as observation as disscussed with apyrva sir																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-03-2020 03:57:47</td><td>SachinPawar</td><td>Completed</td><td>dvr power adapter is faulty so selft supply installed as observation as disscussed with apyrva sir</td><td></td></tr><tr><td>12-03-2020 03:45:57</td><td>SachinPawar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-03-2020 03:45:49</td><td>SachinPawar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-03-2020 03:57:47	SachinPawar	Completed	dvr power adapter is faulty so selft supply installed as observation as disscussed with apyrva sir		12-03-2020 03:45:57	SachinPawar	New		-	12-03-2020 03:45:49	SachinPawar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-03-2020 03:57:47	SachinPawar	Completed	dvr power adapter is faulty so selft supply installed as observation as disscussed with apyrva sir																						
12-03-2020 03:45:57	SachinPawar	New		-																					
12-03-2020 03:45:49	SachinPawar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-11-2020 02:06:11</td><td>Neeraj Chauhan</td><td>there was no HDD in any DVR DVR working 2 supply issue - 1 week and 1 dead</td></tr><tr><td>09-03-2020 01:58:48</td><td>SachinPawar</td><td>survy done and online viewing done on mobile via hik connect</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-11-2020 02:06:11	Neeraj Chauhan	there was no HDD in any DVR DVR working 2 supply issue - 1 week and 1 dead	09-03-2020 01:58:48	SachinPawar	survy done and online viewing done on mobile via hik connect											
Date Time	Technician Name	Remark																							
30-11-2020 02:06:11	Neeraj Chauhan	there was no HDD in any DVR DVR working 2 supply issue - 1 week and 1 dead																							
09-03-2020 01:58:48	SachinPawar	survy done and online viewing done on mobile via hik connect																							