




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5976</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8108303036																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	18-07-2022 12:05:49																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Keval Export Turbe	Customer's Mobile :	8108303036	Name :	Tejas Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	30-07-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1 camera getting on off Outside camera																								
<b>Technician Comment :</b>	one bullet camera outside facing road camera on and off issue. camera kept under observation now it's is working ok camera under observation.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	one bullet camera outside facing road camera on and off issue. camera kept under observation now it's is working ok camera under observation.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-07-2022 03:18:41</td><td>YogeshDesai</td><td>Completed</td><td>one bullet camera outside facing road camera on and off issue. camera kept under observation now it's is working ok camera under observation.</td><td></td></tr><tr><td>18-07-2022 12:07:00</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>18-07-2022 12:05:49</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-07-2022 03:18:41	YogeshDesai	Completed	one bullet camera outside facing road camera on and off issue. camera kept under observation now it's is working ok camera under observation.		18-07-2022 12:07:00	YogeshDesai	New		-	18-07-2022 12:05:49	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
18-07-2022 03:18:41	YogeshDesai	Completed	one bullet camera outside facing road camera on and off issue. camera kept under observation now it's is working ok camera under observation.																						
18-07-2022 12:07:00	YogeshDesai	New		-																					
18-07-2022 12:05:49	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-04-2022 10:53:17</td><td>Shiva Meena</td><td></td></tr><tr><td>07-04-2022 10:23:06</td><td>Neeraj Chauhan</td><td>dvr beep sound issue solved and dvr power adaptor not proper working and New power supply install and recording issue solve camera working okk</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-04-2022 10:53:17	Shiva Meena		07-04-2022 10:23:06	Neeraj Chauhan	dvr beep sound issue solved and dvr power adaptor not proper working and New power supply install and recording issue solve camera working okk											
Date Time	Technician Name	Remark																							
28-04-2022 10:53:17	Shiva Meena																								
07-04-2022 10:23:06	Neeraj Chauhan	dvr beep sound issue solved and dvr power adaptor not proper working and New power supply install and recording issue solve camera working okk																							