




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4146																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8108303036																													
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																										
Ticket Type :	Complain	Date & Time :	29-10-2021 03:54:04																											
Vendor Details :																														
Company Name/Client Name :	Keval Export Mahape	Customer's Mobile :	8108303036	Name :	Tejus Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	CCTV Survey																													
Technician Comment :	CCTV system servey done 5 camera shifted and 3 new camera install with cabling total 8-9 camera																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	CCTV system servey done 5 camera shifted and 3 new camera install with cabling total 8-9 camera																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-02-2022 12:49:46</td><td>Ravi Rajbhar</td><td>Closed</td><td></td><td>-</td></tr><tr><td>29-10-2021 05:24:06</td><td>Ravi Rajbhar</td><td>Completed</td><td>CCTV system servey done 5 camera shifted and 3 new camera install with cabling total 8-9 camera</td><td></td></tr><tr><td>29-10-2021 03:54:20</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>29-10-2021 03:54:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-02-2022 12:49:46	Ravi Rajbhar	Closed		-	29-10-2021 05:24:06	Ravi Rajbhar	Completed	CCTV system servey done 5 camera shifted and 3 new camera install with cabling total 8-9 camera		29-10-2021 03:54:20	Ravi Rajbhar	New		-	29-10-2021 03:54:04	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
16-02-2022 12:49:46	Ravi Rajbhar	Closed		-																										
29-10-2021 05:24:06	Ravi Rajbhar	Completed	CCTV system servey done 5 camera shifted and 3 new camera install with cabling total 8-9 camera																											
29-10-2021 03:54:20	Ravi Rajbhar	New		-																										
29-10-2021 03:54:04	Ravi Rajbhar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-01-2022 07:11:54</td><td>Atique Salmani</td><td>ppm done all working ok dvr SMPS changed and keep it in under observation and also activate boath dvr beep alert and of hhd error and vedeo loss all working ok.</td></tr><tr><td>08-12-2021 10:36:48</td><td>Neeraj Chauhan</td><td>bimatric device install and sandby machines culectch and send to office device working OK.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-01-2022 07:11:54	Atique Salmani	ppm done all working ok dvr SMPS changed and keep it in under observation and also activate boath dvr beep alert and of hhd error and vedeo loss all working ok.	08-12-2021 10:36:48	Neeraj Chauhan	bimatric device install and sandby machines culectch and send to office device working OK.																
Date Time	Technician Name	Remark																												
29-01-2022 07:11:54	Atique Salmani	ppm done all working ok dvr SMPS changed and keep it in under observation and also activate boath dvr beep alert and of hhd error and vedeo loss all working ok.																												
08-12-2021 10:36:48	Neeraj Chauhan	bimatric device install and sandby machines culectch and send to office device working OK.																												