

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2657																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9321756273																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	03-02-2021 10:24:24																						
Vendor Details :																									
Company Name/Client Name :	Atul Tower	Customer's Mobile :	9321756273	Name :	Thakur																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	tv off																								
Technician Comment :	fuse of rack extention burn and also dvr adaptr faulty changed 12volt 5amps smps as adaptor working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	fuse of rack extention burn and also dvr adaptr faulty changed 12volt 5amps smps as adaptor working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-02-2021 12:25:22</td><td>Atique Salmani</td><td>Completed</td><td>fuse of rack extention burn and also dvr adaptr faulty changed 12volt 5amps smps as adaptor working ok.</td><td></td></tr><tr><td>03-02-2021 10:24:41</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>03-02-2021 10:24:24</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-02-2021 12:25:22	Atique Salmani	Completed	fuse of rack extention burn and also dvr adaptr faulty changed 12volt 5amps smps as adaptor working ok.		03-02-2021 10:24:41	Atique Salmani	New		-	03-02-2021 10:24:24	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-02-2021 12:25:22	Atique Salmani	Completed	fuse of rack extention burn and also dvr adaptr faulty changed 12volt 5amps smps as adaptor working ok.																						
03-02-2021 10:24:41	Atique Salmani	New		-																					
03-02-2021 10:24:24	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-12-2020 10:42:10</td><td>Atique Salmani</td><td>ppm comeated 2 cameras stand break need to changed.</td></tr><tr><td>14-12-2020 05:51:14</td><td>Siddhesh Chavan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	29-12-2020 10:42:10	Atique Salmani	ppm comeated 2 cameras stand break need to changed.	14-12-2020 05:51:14	Siddhesh Chavan												
Date Time	Technician Name	Remark																							
29-12-2020 10:42:10	Atique Salmani	ppm comeated 2 cameras stand break need to changed.																							
14-12-2020 05:51:14	Siddhesh Chavan																								