




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5408																																													
Priority :	Low																																												
Created By :	Admin - Apurva Vajaria																																												
Complaint Mob. No. :	9167588545																																												
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																																									
Ticket Type :	Complain	Date & Time :	09-05-2022 11:14:46																																										
Vendor Details :																																													
Company Name/Client Name :	Vimla Villa Vaibhav Sir Home	Customer's Mobile :	9167588545	Name :	Vaibhav Doshi																																								
Address :																																													
Mumbai , , , , Maharashtra																																													
AMC Details :																																													
Expiry Date :	01-01-1970 05:30:00		Type :																																										
Product Name :	CCTV-VDP																																												
Complain :	cctv set up proper to be done and vdp installation as renovation ia Completed																																												
Technician Comment :	change the adpter moniter working ok and tv not installed.																																												
Complain Operator :	Desktop - Apurva Vajaria																																												
Remark :	change the adpter moniter working ok and tv not installed.																																												
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-05-2022 10:11:31</td><td>ChandanYadav</td><td>Completed</td><td></td><td>-</td></tr><tr><td>10-05-2022 04:31:45</td><td>ChandanYadav</td><td>Client Side</td><td>change the adpter moniter working ok and tv not installed.</td><td></td></tr><tr><td>10-05-2022 03:52:32</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>10-05-2022 11:34:14</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>09-05-2022 07:55:46</td><td>ChandanYadav</td><td>Work Pending</td><td>NVR end all dressing done cut cable and recring done 10 cameras plus extender also crimp and online done also vdp installed working ok hdmi extender adaptor issue 5 volt 2 amps need to changed .</td><td></td></tr><tr><td>09-05-2022 11:15:17</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>09-05-2022 11:14:46</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-05-2022 10:11:31	ChandanYadav	Completed		-	10-05-2022 04:31:45	ChandanYadav	Client Side	change the adpter moniter working ok and tv not installed.		10-05-2022 03:52:32	ChandanYadav	New		-	10-05-2022 11:34:14	ChandanYadav	New		-	09-05-2022 07:55:46	ChandanYadav	Work Pending	NVR end all dressing done cut cable and recring done 10 cameras plus extender also crimp and online done also vdp installed working ok hdmi extender adaptor issue 5 volt 2 amps need to changed .		09-05-2022 11:15:17	ChandanYadav	New		-	09-05-2022 11:14:46	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																																									
31-05-2022 10:11:31	ChandanYadav	Completed		-																																									
10-05-2022 04:31:45	ChandanYadav	Client Side	change the adpter moniter working ok and tv not installed.																																										
10-05-2022 03:52:32	ChandanYadav	New		-																																									
10-05-2022 11:34:14	ChandanYadav	New		-																																									
09-05-2022 07:55:46	ChandanYadav	Work Pending	NVR end all dressing done cut cable and recring done 10 cameras plus extender also crimp and online done also vdp installed working ok hdmi extender adaptor issue 5 volt 2 amps need to changed .																																										
09-05-2022 11:15:17	ChandanYadav	New		-																																									
09-05-2022 11:14:46	ChandanYadav	New		-																																									

Previous Complain History :	Date Time	Technician Name	Remark
	31-05-2022 02:39:29	Atique Salmani	
	31-05-2022 10:10:02	Atique Salmani	There is hdmi cable faulty use client hdmi cable temporary .and done in sequence all cameras all cameras working ok.