




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6762																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7506373834																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	04-11-2022 04:00:00																						
Vendor Details :																									
Company Name/Client Name :	Yamunotri Co Op Hsg Society	Customer's Mobile :	7506373834	Name :	Vikash Joshi																				
Address :																									
mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	lift camera again off issue																								
Technician Comment :	B wing lift camera issue resolved by use baloon boath end and it's working ok																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	B wing lift camera issue resolved by use baloon boath end and it's working ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-11-2022 05:47:12</td><td>Atique Salmani</td><td>Completed</td><td>B wing lift camera issue resolved by use baloon boath end and it's working ok</td><td></td></tr><tr><td>05-11-2022 10:23:19</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-11-2022 04:00:05</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-11-2022 05:47:12	Atique Salmani	Completed	B wing lift camera issue resolved by use baloon boath end and it's working ok		05-11-2022 10:23:19	Atique Salmani	New		-	04-11-2022 04:00:05	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-11-2022 05:47:12	Atique Salmani	Completed	B wing lift camera issue resolved by use baloon boath end and it's working ok																						
05-11-2022 10:23:19	Atique Salmani	New		-																					
04-11-2022 04:00:05	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-11-2022 10:26:36</td><td>Atique Salmani</td><td>Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .</td></tr><tr><td>03-11-2022 10:44:34</td><td>PravinJagade</td><td>lift camera working done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-11-2022 10:26:36	Atique Salmani	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .	03-11-2022 10:44:34	PravinJagade	lift camera working done.											
Date Time	Technician Name	Remark																							
05-11-2022 10:26:36	Atique Salmani	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .																							
03-11-2022 10:44:34	PravinJagade	lift camera working done.																							