## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status D	<b>Details :</b> VE11772								
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	7352454804								
Technician Name :	Sonu Kumar		Technician Mobile	8454016444					
Ticket Type :	Complain	omplain Date & Time :		-05-2024 02:48:55					
Vendor Details :									
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir				
Address:									
Mumbai , , , , M	[aharashtra								
AMC Details :									
Expiry Date :	01-01-1970 05:30:00		Type:						
Product Name:	CCTV								
Complain:	302,303,304 3rd floor DVR 1201,202 A, 107 view not clear 502,503,504, 7th floor studio no 5 805, 401,402,403,406, AI IPC All cameras are offline								
Technician Comment :	4th floor 406 / 407 base and braket missing 5th floor 504 camera install 7th floor studio room camera handover to vikas sir 8th floor terrace side 2 camera install and and 1 camera install 4h floor 2 camera angle setting done 3rd floor passage 2 camera angle setting done 2nd floor 206 location change 1st floor passage 2 camera angle setting done								
Complain Operator :	Desktop - Apurva Vajaria								
Remark :	4th floor 406 / 407 base and braket missing 5th floor 504 camera install 7th floor studio room camera handover to vikas sir 8th floor terrace side 2 camera install and and 1 camera install 4h floor 2 camera angle setting done 3rd floor passage 2 camera angle setting done 2nd floor 206 location change 1st floor passage 2 camera angle setting done								

Status History :	Date Time	Technician Name		Status	Remark	Sign	
	05-07-2024 01:44:46	Sonu Kumar	Can	celled		-	
	29-06-2024 05:30:56	Sonu Kumar	Completed		4th floor 406 / 407 base and braket missing 5th floor 504 camera install 7th floor studio room camera handover to vikas sir 8th floor terrace side 2 camera install and and 1 camera install 4h floor 2 camera angle setting done 3rd floor pasage 2 camera angle setting done 2nd floor 206 location change 1st floor passage 2 camera angle setting done		
	29-06-2024 11:16:05	Sonu Kumar	New		-		
	03-06-2024 12:42:30	Sonu Kumar	Nev	New		-	
	31-05-2024 05:53:46	Sonu Kumar	Work Pending		201 and 202 camera reinstall working done 401 402 403 and 404 camera reinstall working done. 406 camera faulty power issue. 502 camera reinstall working done 504 camera falty power issue 503 camera not install because door lock pending. 805 camera check pending door lock Studio room camera check pending door lock. 406 or 504 camera collect need to check office Ground floor 1 DVR offine check pending.		
	30-05-2024 06:43:24	Sonu Kumar	New			-	
Previous Complain	Date Time	Technician N	Name		Remark		
History :	03-07-2024 10:50:1	9:17 Sonu Kumar		1. Ground floor lobby2 1 camera off issue resolved working ok 2 Counselor office 1 camera off issue resolved working ok 3. 5th floor 8 camera off issue resolved working ok 4. Ground floor 2 camera angle setting done 5. 1st floor passage 2 camera angle setting done		ok 3. 5th nd floor 2	
	28-06-2024 12:41:4-	4 Sonu Kumar	1 switch off issue resolved working ok				