

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12562																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	7352454804																													
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																										
Ticket Type :	Complain	Date & Time :	28-08-2024 03:23:49																											
Vendor Details :																														
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	Rahul sir cabin (Management cabin) viewing setting of cameras on screen																													
Technician Comment :	Tv living on and 5 dome camera install all working ok 8 port poe switch installed																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Tv living on and 5 dome camera install all working ok 8 port poe switch installed																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-09-2024 06:01:14</td><td>Sonu Kumar</td><td>Completed</td><td>Tv living on and 5 dome camera install all working ok 8 port poe switch installed</td><td></td></tr><tr><td>04-09-2024 11:45:53</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-08-2024 05:18:22</td><td>Sonu Kumar</td><td>Awaiting Spares</td><td>In Rahul sir cabin view painding because some material required so Its painding .</td><td></td></tr><tr><td>28-08-2024 03:24:12</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-09-2024 06:01:14	Sonu Kumar	Completed	Tv living on and 5 dome camera install all working ok 8 port poe switch installed		04-09-2024 11:45:53	Sonu Kumar	New		-	28-08-2024 05:18:22	Sonu Kumar	Awaiting Spares	In Rahul sir cabin view painding because some material required so Its painding .		28-08-2024 03:24:12	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
04-09-2024 06:01:14	Sonu Kumar	Completed	Tv living on and 5 dome camera install all working ok 8 port poe switch installed																											
04-09-2024 11:45:53	Sonu Kumar	New		-																										
28-08-2024 05:18:22	Sonu Kumar	Awaiting Spares	In Rahul sir cabin view painding because some material required so Its painding .																											
28-08-2024 03:24:12	Sonu Kumar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-09-2024 02:50:26</td><td>ManojPolekar</td><td>20.09.2024 - Main gate 3-4 cameras visibility issue solved</td></tr><tr><td>06-09-2024 03:04:20</td><td>Sonu Kumar</td><td>Ground floor admin1 ip camera swipe to algalog camere in lobby and 6th floor camera off issue resolved working ok and 8th floor 806 out side camera cable faulty</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-09-2024 02:50:26	ManojPolekar	20.09.2024 - Main gate 3-4 cameras visibility issue solved	06-09-2024 03:04:20	Sonu Kumar	Ground floor admin1 ip camera swipe to algalog camere in lobby and 6th floor camera off issue resolved working ok and 8th floor 806 out side camera cable faulty																
Date Time	Technician Name	Remark																												
19-09-2024 02:50:26	ManojPolekar	20.09.2024 - Main gate 3-4 cameras visibility issue solved																												
06-09-2024 03:04:20	Sonu Kumar	Ground floor admin1 ip camera swipe to algalog camere in lobby and 6th floor camera off issue resolved working ok and 8th floor 806 out side camera cable faulty																												