

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15121															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	7352454804														
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985											
Ticket Type :	Complain	Date & Time :	27-06-2025 11:51:13												
Vendor Details :															
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	1)6th floor Studio Room 1 dome replacement camera need to install 2)7th floor staircase 2 - 1 dome replacment camera need to install 3)class no. 507 Admin pc me camera not able to see on software 4)class no. 801 camera offline														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-06-2025 11:51:18</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-06-2025 11:51:18	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign											
27-06-2025 11:51:18	Siddhesh Chavan	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-07-2025 10:57:50</td><td>Neeraj Chauhan</td><td>Lift camera laging issue solved camera under observation 801 offline issue solved camera working okk</td></tr><tr><td>14-07-2025 11:43:33</td><td>Atique Salmani</td><td>601 a angel set Studio 605 angel set Poe switch new installation done Gate nmbr 5 1 pair 1and 2 faulty so swap cable and recrimping boath side angel set working ok. Also boss cabin view off issue resolved working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-07-2025 10:57:50	Neeraj Chauhan	Lift camera laging issue solved camera under observation 801 offline issue solved camera working okk	14-07-2025 11:43:33	Atique Salmani	601 a angel set Studio 605 angel set Poe switch new installation done Gate nmbr 5 1 pair 1and 2 faulty so swap cable and recrimping boath side angel set working ok. Also boss cabin view off issue resolved working ok.	
Date Time	Technician Name	Remark													
21-07-2025 10:57:50	Neeraj Chauhan	Lift camera laging issue solved camera under observation 801 offline issue solved camera working okk													
14-07-2025 11:43:33	Atique Salmani	601 a angel set Studio 605 angel set Poe switch new installation done Gate nmbr 5 1 pair 1and 2 faulty so swap cable and recrimping boath side angel set working ok. Also boss cabin view off issue resolved working ok.													