




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5084																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7666670527																								
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																					
Ticket Type :	Complain	Date & Time :	26-03-2022 10:15:23																						
Vendor Details :																									
Company Name/Client Name :	Ambica Society Consultancy	Customer's Mobile :	7666670527	Name :	Vimal Chauhan																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	EPABX																								
Complain :	Key-phone on display no number issue																								
Technician Comment :	key phone working ok and all line and co line no issues for Clint side																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	key phone working ok and all line and co line no issues for Clint side																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-03-2022 07:35:37</td><td>Siddhesh Chavan</td><td>Completed</td><td>key phone working ok and all line and co line no issues for Clint side</td><td></td></tr><tr><td>26-03-2022 10:15:36</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>26-03-2022 10:15:23</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-03-2022 07:35:37	Siddhesh Chavan	Completed	key phone working ok and all line and co line no issues for Clint side		26-03-2022 10:15:36	Siddhesh Chavan	New		-	26-03-2022 10:15:23	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-03-2022 07:35:37	Siddhesh Chavan	Completed	key phone working ok and all line and co line no issues for Clint side																						
26-03-2022 10:15:36	Siddhesh Chavan	New		-																					
26-03-2022 10:15:23	Siddhesh Chavan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-03-2022 10:16:01</td><td>Munna Gupta</td><td>Epbx system need to installation and programing . Epbx system working properly.</td></tr><tr><td>04-03-2022 11:49:11</td><td>Siddhesh Chavan</td><td>cpbx system working ok co line incoming issue for client side and access working ok but Clint off door lock and dvr off because dvr adapter issue change supply and dvr working ok and all camera working ok and install ivms 4200 software new pc and add dives and need to change bnc dvr side</td></tr></tbody></table>					Date Time	Technician Name	Remark	11-03-2022 10:16:01	Munna Gupta	Epbx system need to installation and programing . Epbx system working properly.	04-03-2022 11:49:11	Siddhesh Chavan	cpbx system working ok co line incoming issue for client side and access working ok but Clint off door lock and dvr off because dvr adapter issue change supply and dvr working ok and all camera working ok and install ivms 4200 software new pc and add dives and need to change bnc dvr side											
Date Time	Technician Name	Remark																							
11-03-2022 10:16:01	Munna Gupta	Epbx system need to installation and programing . Epbx system working properly.																							
04-03-2022 11:49:11	Siddhesh Chavan	cpbx system working ok co line incoming issue for client side and access working ok but Clint off door lock and dvr off because dvr adapter issue change supply and dvr working ok and all camera working ok and install ivms 4200 software new pc and add dives and need to change bnc dvr side																							