







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10219</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9819990297																																		
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-12-2023 10:46:22																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																														
<b>Address :</b>																																			
Mumbai , , , , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																															
<b>Product Name :</b>	CCTV																																		
<b>Complain :</b>	A-603 - when bell press not able to see on screen need to send with pCB - 750/- charges - 9619836277																																		
<b>Technician Comment :</b>	video door phone issue resolved and ok working done and big pcb install with connect in bell and 750 cash collect																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	video door phone issue resolved and ok working done and big pcb install with connect in bell and 750 cash collect																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-12-2023 11:33:01</td><td>Ravi Rajbhar</td><td>Completed</td><td>video door phone issue resolved and ok working done and big pcb install with connect in bell and 750 cash collect</td><td></td></tr><tr><td>25-12-2023 10:31:16</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>09-12-2023 02:49:14</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>603 vdp PCB not install because bell side no neutral cable so work pending</td><td></td></tr><tr><td>09-12-2023 10:33:53</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>08-12-2023 05:06:51</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-12-2023 11:33:01	Ravi Rajbhar	Completed	video door phone issue resolved and ok working done and big pcb install with connect in bell and 750 cash collect		25-12-2023 10:31:16	Ravi Rajbhar	New		-	09-12-2023 02:49:14	Ravi Rajbhar	Work Pending	603 vdp PCB not install because bell side no neutral cable so work pending		09-12-2023 10:33:53	Ravi Rajbhar	New		-	08-12-2023 05:06:51	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
25-12-2023 11:33:01	Ravi Rajbhar	Completed	video door phone issue resolved and ok working done and big pcb install with connect in bell and 750 cash collect																																
25-12-2023 10:31:16	Ravi Rajbhar	New		-																															
09-12-2023 02:49:14	Ravi Rajbhar	Work Pending	603 vdp PCB not install because bell side no neutral cable so work pending																																
09-12-2023 10:33:53	Ravi Rajbhar	New		-																															
08-12-2023 05:06:51	Ravi Rajbhar	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-12-2023 10:52:25</td><td>Sonu Kumar</td><td>Recording not seen in acjact time</td></tr><tr><td>17-11-2023 12:08:34</td><td>Ravi Rajbhar</td><td>a wing 703 ,704 and 603 video door phone issue resolved and ok working done and 703 out door camera reinstall</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-12-2023 10:52:25	Sonu Kumar	Recording not seen in acjact time	17-11-2023 12:08:34	Ravi Rajbhar	a wing 703 ,704 and 603 video door phone issue resolved and ok working done and 703 out door camera reinstall																					
Date Time	Technician Name	Remark																																	
01-12-2023 10:52:25	Sonu Kumar	Recording not seen in acjact time																																	
17-11-2023 12:08:34	Ravi Rajbhar	a wing 703 ,704 and 603 video door phone issue resolved and ok working done and 703 out door camera reinstall																																	