




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1706</b>																														
<b>Priority :</b>	High																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9819990297																													
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	18-08-2020 10:27:36																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Bhoomi Ganga Enclave A Wing	<b>Customer's Mobile :</b>	9819990297	<b>Name :</b>	Vipul Bhai																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	30-09-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																										
<b>Product Name :</b>	Access																													
<b>Complain :</b>	need to start Lock																													
<b>Technician Comment :</b>	Bhoomi A Wing biometric attendance machine started and and lock issue solved and flat no 303 vdp working ok and 702 wdp started and 704 continue ball issue solved																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	Bhoomi A Wing biometric attendance machine started and and lock issue solved and flat no 303 vdp working ok and 702 wdp started and 704 continue ball issue solved																													
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>18-08-2020 06:31:40</td> <td>Siddhesh Chavan</td> <td>Completed</td> <td>Bhoomi A Wing biometric attendance machine started and and lock issue solved and flat no 303 vdp working ok and 702 wdp started and 704 continue ball issue solved</td> <td></td> </tr> <tr> <td>18-08-2020 06:12:37</td> <td>Siddhesh Chavan</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>18-08-2020 10:29:12</td> <td>Siddhesh Chavan</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>18-08-2020 10:27:37</td> <td>Siddhesh Chavan</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	18-08-2020 06:31:40	Siddhesh Chavan	Completed	Bhoomi A Wing biometric attendance machine started and and lock issue solved and flat no 303 vdp working ok and 702 wdp started and 704 continue ball issue solved		18-08-2020 06:12:37	Siddhesh Chavan	New		-	18-08-2020 10:29:12	Siddhesh Chavan	New		-	18-08-2020 10:27:37	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
18-08-2020 06:31:40	Siddhesh Chavan	Completed	Bhoomi A Wing biometric attendance machine started and and lock issue solved and flat no 303 vdp working ok and 702 wdp started and 704 continue ball issue solved																											
18-08-2020 06:12:37	Siddhesh Chavan	New		-																										
18-08-2020 10:29:12	Siddhesh Chavan	New		-																										
18-08-2020 10:27:37	Siddhesh Chavan	New		-																										
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>21-10-2020 11:42:29</td> <td>Ravi Rajbhar</td> <td>bhoomi a wing 302 603 102 issue resolved and ok working done</td> </tr> <tr> <td>05-10-2020 11:10:04</td> <td></td> <td>reinstallation need work.</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	21-10-2020 11:42:29	Ravi Rajbhar	bhoomi a wing 302 603 102 issue resolved and ok working done	05-10-2020 11:10:04		reinstallation need work.																
Date Time	Technician Name	Remark																												
21-10-2020 11:42:29	Ravi Rajbhar	bhoomi a wing 302 603 102 issue resolved and ok working done																												
05-10-2020 11:10:04		reinstallation need work.																												