## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE2158 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9819990297 **No. : Technician Name** Rishi Desai **Technician Mobile** 8369234074 Complain Date & Time : 02-11-2020 02:58:53 **Ticket Type :** Vendor Details : Bhoomi Ganga Customer's Mobile 9819990297 Vipul Bhai Company Name : Name/Client Name Enclave A Wing Address : Mumbai,,,, Maharashtra **AMC Details :** 31-12-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: to show recording Playback shown to concern person Mr. Vrajesh also locked the File in dvr Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Playback shown to concern person Mr. Vrajesh also locked the File in dvr **Status History : Technician Name Date Time** Status Remark Sign 02-11-2020 03:03:06 RishiDesai Completed Playback shown to concern person Mr. Vrajesh also Ð locked the File in dvr RishiDesai 02-11-2020 02:59:17 New 02-11-2020 02:58:53 RishiDesai New **Previous Technician Name Date Time** Remark **Complain History** Parshva Shah 08-12-2020 03:31:14 08-12-2020 09:55:07 YogeshDesai lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats