




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2254</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819990297																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-11-2020 05:20:00																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Bhoomi Ganga Enclave A Wing	<b>Customer's Mobile :</b>	9819990297	<b>Name :</b>	Vipul Bhai																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	31-12-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	cabling 101 603 vdp installation																								
<b>Technician Comment :</b>	101 flat cable change and lobby video issue solved and 601 vdp return and working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	101 flat cable change and lobby video issue solved and 601 vdp return and working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-11-2020 10:40:43</td><td>Siddhesh Chavan</td><td>Completed</td><td>101 flat cable change and lobby video issue solved and 601 vdp return and working ok</td><td></td></tr><tr><td>20-11-2020 05:20:52</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>20-11-2020 05:20:00</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-11-2020 10:40:43	Siddhesh Chavan	Completed	101 flat cable change and lobby video issue solved and 601 vdp return and working ok		20-11-2020 05:20:52	Siddhesh Chavan	New		-	20-11-2020 05:20:00	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-11-2020 10:40:43	Siddhesh Chavan	Completed	101 flat cable change and lobby video issue solved and 601 vdp return and working ok																						
20-11-2020 05:20:52	Siddhesh Chavan	New		-																					
20-11-2020 05:20:00	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-12-2020 03:31:14</td><td>Parshva Shah</td><td></td></tr><tr><td>08-12-2020 09:55:07</td><td>YogeshDesai</td><td>lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-12-2020 03:31:14	Parshva Shah		08-12-2020 09:55:07	YogeshDesai	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats											
Date Time	Technician Name	Remark																							
08-12-2020 03:31:14	Parshva Shah																								
08-12-2020 09:55:07	YogeshDesai	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats																							