




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3805</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9819990297																																		
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-09-2021 05:36:00																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																														
<b>Address :</b>																																			
Mumbai , , , , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																															
<b>Product Name :</b>	VDP																																		
<b>Complain :</b>	a-705 nC01 need to change																																		
<b>Technician Comment :</b>	70,5 new vdp sceen install faulty screen also collect to office with canfiguration in lobby panel and working done																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	70,5 new vdp sceen install faulty screen also collect to office with canfiguration in lobby panel and working done																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-09-2021 03:22:12</td><td>Ravi Rajbhar</td><td>Completed</td><td>70,5 new vdp sceen install faulty screen also collect to office with canfiguration in lobby panel and working done</td><td></td></tr><tr><td>14-09-2021 03:19:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-09-2021 03:11:31</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>08-09-2021 05:36:13</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>08-09-2021 05:36:00</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-09-2021 03:22:12	Ravi Rajbhar	Completed	70,5 new vdp sceen install faulty screen also collect to office with canfiguration in lobby panel and working done		14-09-2021 03:19:01	Ravi Rajbhar	New		-	13-09-2021 03:11:31	Ravi Rajbhar	New		-	08-09-2021 05:36:13	Ravi Rajbhar	New		-	08-09-2021 05:36:00	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
14-09-2021 03:22:12	Ravi Rajbhar	Completed	70,5 new vdp sceen install faulty screen also collect to office with canfiguration in lobby panel and working done																																
14-09-2021 03:19:01	Ravi Rajbhar	New		-																															
13-09-2021 03:11:31	Ravi Rajbhar	New		-																															
08-09-2021 05:36:13	Ravi Rajbhar	New		-																															
08-09-2021 05:36:00	Ravi Rajbhar	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-09-2021 06:21:11</td><td>Ravi Rajbhar</td><td>705 vdp check and cantinue ringing issue resolved cable check both side NC 01 chenge but vdp under Observation</td></tr><tr><td>28-08-2021 03:38:11</td><td>YogeshDesai</td><td>Ppm work of CCTV completed all cameras are working recording is on in both dvr . ppm work done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-09-2021 06:21:11	Ravi Rajbhar	705 vdp check and cantinue ringing issue resolved cable check both side NC 01 chenge but vdp under Observation	28-08-2021 03:38:11	YogeshDesai	Ppm work of CCTV completed all cameras are working recording is on in both dvr . ppm work done.																					
Date Time	Technician Name	Remark																																	
04-09-2021 06:21:11	Ravi Rajbhar	705 vdp check and cantinue ringing issue resolved cable check both side NC 01 chenge but vdp under Observation																																	
28-08-2021 03:38:11	YogeshDesai	Ppm work of CCTV completed all cameras are working recording is on in both dvr . ppm work done.																																	