Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5227 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9819990297 **No. :** Technician Ravi Rajbhar **Technician Mobile** 8080922965 Name : Complain 16-04-2022 11:27:43 **Ticket Type :** Date & Time : **Vendor Details :** Bhoomi Ganga Customer's Mobile 9819990297 Vipul Bhai Company Name : Name/Client Enclave A Wing Name : **Address** : Mumbai,,,, Maharashtra **AMC Details :** 31-12-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV **Complain**: 203, 401 and 403 outdoor camera issue A wing 203 out door camera issue resolved 101 issue resolved 401 issue resolved 403 nc01 Technician change and check (403 Champlain pending) **Comment** : Complain Desktop - Apurva Vajaria **Operator** : A wing 203 out door camera issue resolved 101 issue resolved 401 issue resolved 403 nc01 **Remark** : change and check (403 Champlain pending) **Status History : Date Time Technician Name** Status Remark Sign 16-04-2022 03:32:39 Ravi Rajbhar Completed A wing 203 out door camera issue resolved 101 issue resolved 401 issue resolved 403 nc01 change and check (403 Champlain pending) 16-04-2022 11:28:59 Ravi Rajbhar New 16-04-2022 11:27:43 Ravi Rajbhar New **Previous Technician Name Date Time** Remark Complain **History** : 18-04-2022 06:28:40 Siddhesh Chavan 403 vdp issue resolved Looby video issue resolved 05-04-2022 03:55:53 Atique Salmani 201 cable was disconnected reconnect and readd flate nmbr working ok and tv plug point loose so it was off now working ok.