










Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6367																																													
Priority :	Low																																												
Created By :	Admin - Apurva Vajaria																																												
Complaint Mob. No. :	9819990297																																												
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																																									
Ticket Type :	Complain	Date & Time :	13-09-2022 05:17:14																																										
Vendor Details :																																													
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																																								
Address :																																													
Mumbai , , , , Maharashtra																																													
AMC Details :																																													
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																																									
Product Name :	CCTV																																												
Complain :	A-702 VDP continuously ringing issue																																												
Technician Comment :	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.																																												
Complain Operator :	Desktop - Apurva Vajaria																																												
Remark :	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.																																												
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-09-2022 05:49:53</td><td>YogeshDesai</td><td>Completed</td><td>camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.</td><td></td></tr><tr><td>21-09-2022 05:45:20</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>16-09-2022 04:47:57</td><td>YogeshDesai</td><td>Work Pending</td><td>out door camera continue bell issue out door camera take to office for checking</td><td></td></tr><tr><td>16-09-2022 10:41:42</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>13-09-2022 05:28:14</td><td>YogeshDesai</td><td>Work Pending</td><td>702 vdp continuously ringing issue not sloved work pending.</td><td></td></tr><tr><td>13-09-2022 05:17:28</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>13-09-2022 05:17:14</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-09-2022 05:49:53	YogeshDesai	Completed	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.		21-09-2022 05:45:20	YogeshDesai	New		-	16-09-2022 04:47:57	YogeshDesai	Work Pending	out door camera continue bell issue out door camera take to office for checking		16-09-2022 10:41:42	YogeshDesai	New		-	13-09-2022 05:28:14	YogeshDesai	Work Pending	702 vdp continuously ringing issue not sloved work pending.		13-09-2022 05:17:28	YogeshDesai	New		-	13-09-2022 05:17:14	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																																									
21-09-2022 05:49:53	YogeshDesai	Completed	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.																																										
21-09-2022 05:45:20	YogeshDesai	New		-																																									
16-09-2022 04:47:57	YogeshDesai	Work Pending	out door camera continue bell issue out door camera take to office for checking																																										
16-09-2022 10:41:42	YogeshDesai	New		-																																									
13-09-2022 05:28:14	YogeshDesai	Work Pending	702 vdp continuously ringing issue not sloved work pending.																																										
13-09-2022 05:17:28	YogeshDesai	New		-																																									
13-09-2022 05:17:14	YogeshDesai	New		-																																									

Previous Complain History :			
	Date Time	Technician Name	Remark
	19-09-2022 02:53:06	Sonu Kumar	2 camera issue resolved working ok and 4 BNC used and 6th floor camera missing
	13-09-2022 04:17:00	Siddhesh Chavan	vdp and out door camera working ok 6 floor distributor to flat vdp side cat 6 cable issue need to change cable