Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6546 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9819990297 **No. : Technician Name** Siddhesh Chavan **Technician Mobile** 8080922985 Complain 10-10-2022 03:06:34 **Ticket Type : Date & Time : Vendor Details :** Bhoomi Ganga Customer's Mobile 9819990297 Name : Vipul Bhai Company Name/Client Name Enclave A Wing Address : Mumbai,,,, Maharashtra **AMC Details :** 31-12-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** VDP Flat no. 501 vdp issue and need to add fingerprint of 1 person in biometric of same flat **Complain**: 501 vdp out door camera Bell issue resolved and working ok and one person finger adding done Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 501 vdp out door camera Bell issue resolved and working ok and one person finger adding done **Status History : Date Time Technician Name** Status Remark Sign 10-10-2022 05:03:33 Siddhesh Chavan Completed 501 vdp out door camera Bell , ¢Ø issue resolved and working ok and one person finger adding 1/ done Siddhesh Chavan 10-10-2022 03:06:47 New 10-10-2022 03:06:34 Siddhesh Chavan New **Previous Date Time** Technician Name Remark Complain 17-10-2022 05:20:12 Siddhesh Chavan History : 702 vdp video issue resolved and lobby video working ok 15-10-2022 01:11:25 Siddhesh Chavan 301 lobby video view issue resolved and 2 nd and 3 rd floor staircase side video disubtr change and 2 nd and 3 floor lobby video issue resolved