




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12632																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9769910586																			
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																
Ticket Type :	Complain	Date & Time :	03-09-2024 01:00:18																	
Vendor Details :																				
Company Name/Client Name :	Glow Star CC7070	Customer's Mobile :	9769910586	Name :	Vishwas Mehta															
Address :																				
Mumbai , Bandra Kurla Complex, Bandra East, Mumbai, Maharashtra, India , , Maharashtra																				
AMC Details :																				
Expiry Date :	26-08-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	Access																			
Complain :	lock not working																			
Technician Comment :	Main door lock alignment issue solve																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Main door lock alignment issue solve																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-09-2024 05:37:36</td><td>MayurYadav</td><td>Completed</td><td>Main door lock alignment issue solve</td><td></td></tr><tr><td>04-09-2024 10:49:02</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-09-2024 05:37:36	MayurYadav	Completed	Main door lock alignment issue solve		04-09-2024 10:49:02	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
04-09-2024 05:37:36	MayurYadav	Completed	Main door lock alignment issue solve																	
04-09-2024 10:49:02	MayurYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-08-2024 12:02:47</td><td>Ravi Rajbhar</td><td>inbio 4 door panal install with configuration done and 8 parson finger add to all divice and 8 card add to all divice and software install essl 3.5 - Please refer ticket no. VE12434 - wrongly updated in other ticket</td></tr><tr><td>19-06-2024 03:07:21</td><td>Atique Salmani</td><td>There is issue in pannel some time it's working some time not working pannel is full rishted by cockroach so need to cable dress also first cctv and access.its too mash of cable .</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-08-2024 12:02:47	Ravi Rajbhar	inbio 4 door panal install with configuration done and 8 parson finger add to all divice and 8 card add to all divice and software install essl 3.5 - Please refer ticket no. VE12434 - wrongly updated in other ticket	19-06-2024 03:07:21	Atique Salmani	There is issue in pannel some time it's working some time not working pannel is full rishted by cockroach so need to cable dress also first cctv and access.its too mash of cable .						
Date Time	Technician Name	Remark																		
13-08-2024 12:02:47	Ravi Rajbhar	inbio 4 door panal install with configuration done and 8 parson finger add to all divice and 8 card add to all divice and software install essl 3.5 - Please refer ticket no. VE12434 - wrongly updated in other ticket																		
19-06-2024 03:07:21	Atique Salmani	There is issue in pannel some time it's working some time not working pannel is full rishted by cockroach so need to cable dress also first cctv and access.its too mash of cable .																		