Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE2042 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9769910586 **No.** : **Technician Name** Yogesh Desai **Technician Mobile** 8080922963 Complain 17-10-2020 12:23:09 **Ticket Type :** Date & Time : **Vendor Details :** Glow Star Customer's Mobile 9769910586 Vishwas Mehta Company Name : Name/Client Name CC7070 Address : Mumbai , Bandra Kurla Complex, Bandra East, Mumbai, Maharashtra, India , , , Maharashtra **AMC Details :** 19-05-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV **Complain**: cable dressing there is no smash of DVR or excess or intercom the smash is of internet provider Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : there is no smash of DVR or excess or intercom the smash is of internet provider **Status History : Date Time Technician Name** Status Remark Sign 17-10-2020 05:03:43 YogeshDesai Completed there is no smash of DVR or excess or intercom the 10221 smash is of internet provider 17-10-2020 12:23:25 YogeshDesai New 17-10-2020 12:23:09 YogeshDesai New Previous **Date Time Technician Name** Remark Complain 01-10-2020 YashDoshi Checked 4 door controller, connected with Laptop through Rj45 **History** : 06:17:51 patch cord , The device is showing in software but while adding the device it remains under progress for long time. so unable to clear the data , Hence work is pending 22-09-2020 Atique Salmani only one camera changed becoz second is working properly so 12:29:53 changed only one and reset date n time and also frame bit now 12 cameras working ok. also 2 Lbracket installed.