

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13099																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8080488068																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	24-10-2024 12:13:31																	
Vendor Details :																				
Company Name/Client Name :	Rudra Securities	Customer's Mobile :	8080488068	Name :	Yash Doshi															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	Site - Kandivali - 3-4 flats intercom issue																			
Technician Comment :	Flat no 1802 cable missing junction Flat no 1001 pending clients side 301 issue resolved 302 issue resolved 202 issue resolved 502 issue resolved Security reception cable faulty need to change																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Flat no 1802 cable missing junction Flat no 1001 pending clients side 301 issue resolved 302 issue resolved 202 issue resolved 502 issue resolved Security reception cable faulty need to change																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2024 05:28:35</td><td>Ravi Rajbhar</td><td>Completed</td><td>Flat no 1802 cable missing junction Flat no 1001 pending clients side 301 issue resolved 302 issue resolved 202 issue resolved 502 issue resolved Security reception cable faulty need to change</td><td></td></tr><tr><td>24-10-2024 04:07:17</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2024 05:28:35	Ravi Rajbhar	Completed	Flat no 1802 cable missing junction Flat no 1001 pending clients side 301 issue resolved 302 issue resolved 202 issue resolved 502 issue resolved Security reception cable faulty need to change		24-10-2024 04:07:17	Ravi Rajbhar	New		-
	Date Time	Technician Name	Status	Remark	Sign															
	24-10-2024 05:28:35	Ravi Rajbhar	Completed	Flat no 1802 cable missing junction Flat no 1001 pending clients side 301 issue resolved 302 issue resolved 202 issue resolved 502 issue resolved Security reception cable faulty need to change																
24-10-2024 04:07:17	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-02-2024 11:30:06</td><td>Ravi Rajbhar</td><td>lift intercom start and ok working done programming 2C - 84 ,83 2B- 81 ,82 2A - 85 ,86 rj 11 used - 6 connector</td></tr><tr><td>15-12-2023 02:53:44</td><td>Siddhesh Chavan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	09-02-2024 11:30:06	Ravi Rajbhar	lift intercom start and ok working done programming 2C - 84 ,83 2B- 81 ,82 2A - 85 ,86 rj 11 used - 6 connector	15-12-2023 02:53:44	Siddhesh Chavan							
	Date Time	Technician Name	Remark																	
	09-02-2024 11:30:06	Ravi Rajbhar	lift intercom start and ok working done programming 2C - 84 ,83 2B- 81 ,82 2A - 85 ,86 rj 11 used - 6 connector																	
15-12-2023 02:53:44	Siddhesh Chavan																			