

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4793																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9022376306																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	New Installation	Date & Time :	16-02-2022 10:32:32																						
Vendor Details :																									
Company Name/Client Name :	Rudra Heights	Customer's Mobile :	9022376306	Name :	Yash Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	1 lobby camera need to start																								
Technician Comment :	use separate SMPS for terrace camera and issue resolved all working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	use separate SMPS for terrace camera and issue resolved all working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-02-2022 10:43:27</td><td>Atique Salmani</td><td>Completed</td><td>use separate SMPS for terrace camera and issue resolved all working ok.</td><td></td></tr><tr><td>16-02-2022 10:33:09</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>16-02-2022 10:32:32</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-02-2022 10:43:27	Atique Salmani	Completed	use separate SMPS for terrace camera and issue resolved all working ok.		16-02-2022 10:33:09	Atique Salmani	New		-	16-02-2022 10:32:32	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-02-2022 10:43:27	Atique Salmani	Completed	use separate SMPS for terrace camera and issue resolved all working ok.																						
16-02-2022 10:33:09	Atique Salmani	New		-																					
16-02-2022 10:32:32	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-02-2022 11:46:42</td><td>Ravi Rajbhar</td><td>total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-02-2022 11:46:42	Ravi Rajbhar	total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby														
Date Time	Technician Name	Remark																							
14-02-2022 11:46:42	Ravi Rajbhar	total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby																							