Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3943 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 7021711644 **No. : Technician Name** Neeraj Chauhan **Technician Mobile** 8898885764 Complain 30-09-2021 05:03:57 **Ticket Type : Date & Time :** Vendor Details : 7021711644 Kamal Apt CHSL Customer's Mobile Yogesh Sir Company Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: HDMI Switcher installation 1 nos new hdmi switcher installation done and working okk. Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 1 nos new hdmi switcher installation done and working okk. **Status History : Technician Name Date Time** Status Remark Sign 30-09-2021 05:10:08 Neeraj Chauhan Completed 1 nos new hdmi switcher installation done and working okk. 30-09-2021 05:04:35 Neeraj Chauhan New 30-09-2021 05:03:57 Neeraj Chauhan New Previous Date Time **Technician Name** Remark **Complain History** 13-07-2023 Shiva Meena Xtedndar done oninstalled TV ok wark complete 11:33:36 26-05-2023 Atique Salmani One camera back side gate Dlink bullet camera installation 12:05:11 done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.