Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE2090								
Priority:	High							
Created By:	Customer - Amar Sir							
Complaint Mob. No. :	9825166631							
Technician Name :				Technician Mobile :				
Ticket Type:	Complain Date & Time :			23-10-2020 12:33:31				
Vendor Details :								
Company Name/Client Name :	Concentrix Services India Pvt Ltd - Alembic	Customer's Mobile :		9825166631		Name :	Amar Sir	
Address:								
gujrat , , , 390003 , Maharashtra								
AMC Details:								
Expiry Date :	01-01-1970 05:30:00			Type:				
Product Name:	Amc							
Complain:	ODC emergency exit camera image showing blurred and sbic emergency exit camera location changed. Please resolve the issue							
Technician Comment:								
Complain Operator :	Desktop - Amar Sir							
Remark:	Reconnected camera and alignment of camera done							
Status History :	Date Time		Technician Name		Status	Rema	rk	Sign
	24-10-2020 03:48:11				Completed			-
	23-10-2020 12:33:31		New		New			-
Previous Complain History :	Date Time Technician Name		Remark					
	08-10-2020 02:48:40			dhrumil visited have checked the hdd reconnected cables wporking fine				
	08-10-2020 01:35:06			Dhrumil Visited the site and have resolved the same. have replaced the camera given at the location				